

SUMMARY OF NOTES FROM FACILITIES REVIEWS MARCH/APRIL 2006

CATEGORY	BUILDING #	CONCERN	NOTES
SAFETY	2	Better ventilation needed in Chemistry Labs.	
SAFETY	2	2207: Mold issues	Part of current bond project.
SAFETY	2	Chemistry office is located in stockroom where chemicals are stored – another location for office would be safer and preferred.	
SAFETY	2	2317/2318: Need exhaust duct to improve ventilation.	
SAFETY	2	Chemistry Stockroom: Protection bars need to be installed for stockroom shelving.	
SAFETY	2	Asphalt pathway is a tripping hazard.	Part of current bond project.
SAFETY	2	The vents send chemical smells from the chemical and photo labs.	
SAFETY	3	The back stairwell is very dark and needs better lighting.	
SAFETY	3	The back stairwell steps become slippery when wet.	
SAFETY	3	Maps lying on the classroom floor have posed a tripping hazard.	Faculty to check with Dean about finding storage space.
SAFETY	3	3201: Some chairs are unsafe to sit in.	
SAFETY	6	Stairwells collect water during rain and can become slippery.	
SAFETY	8	General Bad air quality on the 3rd floor; smells of chemicals.	
SAFETY	8	8304: Fire blanket needs to be remounted.	
SAFETY	8	Eye wash stations and prep areas needed in every lab.	
SAFETY	8	GFI on all electrical receptacles.	
SAFETY	8	Drench shower in lab – need a shower in each corner of the room.	
SAFETY	8	8317: Office too confined.	
SAFETY	8	8314: Cadaver needs a non-skid floor (need to be able to mop).	
SAFETY	8	8314/8323: Relocate gas/air/electric to top of table in labs to eliminate tripping hazards.	
SAFETY	8	8314: Need plexi-glass enclosure for cadaver.	
SAFETY	8	8314: Cadaver needs a separate room and floor drain; has a bad vent and needs better refrigeration.	
SAFETY	8	3-3R stairway too dark.	
SAFETY	8	Non-skid paint needed on all concrete floors in labs.	
SAFETY	9	9101/9103/9106/9109: Continued flooding in rooms during rain	Part of current bond project.

SAFETY	9	Removal of Eucalyptus Trees & replace with CA native trees.	
SAFETY	9	Pathway from Training Room to Field House has tripping hazards.	
SAFETY	9	Stairwell has dark areas – shadow in middle of the stairs.	
SAFETY	Hyman Hall	Offices are too dark – hard to see when leaving in the evening; all lighting is on one switch and turns off all at once.	
SAFETY	Hyman Hall	Restrooms floors have sitting water from sinks and counters; due to design issue.	
SAFETY	Hyman Hall	President Treadway suggested an overall Ergonomic Review of the building.	
SAFETY	Smith Center	Lobby door mechanisms are malfunctioning.	
SAFETY	Smith Center	West Lobby door emergency exit does not fully open.	
SAFETY	Smith Center	Red tiles are slippery.	
FACILITIES/IT STAFF	2	2310: Podium needs moved.	
FACILITIES/IT STAFF	2	Chemistry Labs: Very cold as well as on 3rd Floor Offices.	
FACILITIES/IT STAFF	3	Projector needed.	
FACILITIES/IT STAFF	3	Spotlights wanted for interpreters and instructors when lights are down for overhead projection lessons, videos, etc.	
FACILITIES/IT STAFF	6	6106: 50% classroom/50% storage; materials need to be secured. A door installation was suggested.	
FACILITIES/IT STAFF	6	Old computer equipment is piled on the 3rd floor; request for these to be removed.	
FACILITIES/IT STAFF	6	6205/6304: Discarded student desks at the back of these classrooms; request made for these items to be removed.	
FACILITIES/IT STAFF	8	8304/8314: Poor water pressure; hot and cold lines need work.	
FACILITIES/IT STAFF	8	8304: Sewer smell from floor drain.	
FACILITIES/IT STAFF	8	8323: Sink drain is slow; need more sink space; faucet leak.	
FACILITIES/IT STAFF	8	8109: Water leaking from the ceiling.	Part of current bond project.
FACILITIES/IT STAFF	8	General storage shortage.	
FACILITIES/IT STAFF	8	Distilled water bottle needs securing.	
FACILITIES/IT STAFF	8	8201: Under-counter Dishwasher needs installation; Wall mount; CO2 Canister.	In Process of Receiving Proposals.
FACILITIES/IT STAFF	8	8203: Bats need attention under eaves.	
FACILITIES/IT STAFF	8	8203: Temperature too hot in spring time.	
FACILITIES/IT STAFF	8	Too many chairs – lower the number of chairs per classroom.	
FACILITIES/IT STAFF	8	8304: Outside door needs replacing.	Part of current bond project.

FACILITIES/IT STAFF	8	8109: Door Replacement	Part of current bond project.
FACILITIES/IT STAFF	8	3rd Floor Restrooms need shelves; 3rd floor Women's Restroom needs lock to work.	
FACILITIES/IT STAFF	8	8304: Check outlets to see if they have power.	
FACILITIES/IT STAFF	8	8109: Install weather station.	
FACILITIES/IT STAFF	8	All exhaust fans need hard wire; too noisy.	
FACILITIES/IT STAFF	8	8305: HVAC issues – too cold.	
FACILITIES/IT STAFF	9	Hanging lights need cleaning.	
FACILITIES/IT STAFF	9	HVAC issues – too hot everywhere but Dance room – supplemental heating needed there.	
FACILITIES/IT STAFF	9	9304: too cold.	
FACILITIES/IT STAFF	9	Mats needed at entrances.	
FACILITIES/IT STAFF	Hyman Hall	118: Nursing classroom is used for 5-8 hrs at a time and the climate is very hot, not conducive for teaching/learning.	
FACILITIES/IT STAFF	Hyman Hall	116: Too cold during the week, but most weekends it seems the room is not even on an HVAC schedule and the air is not on at all; very hot in the summertime.	
FACILITIES/IT STAFF	Hyman Hall	118: Damaged power supplies.	
FACILITIES/IT STAFF	Smith Center	Parking Lot W lines need repainted.	
REQUESTED NEEDS	2	Chamber way hallway is very dark; needs more lighting.	
REQUESTED NEEDS	2	Sound bleed into 2125 and 2133 coming from 2201	Possibly a scheduling issue?
REQUESTED NEEDS	2	2310: Windows are too high to open; would like fresh air to circulate in the summer.	
REQUESTED NEEDS	2	General space needed for backpacks/coats.	
REQUESTED NEEDS	2	Stockroom door needed.	
REQUESTED NEEDS	2	Chemistry Dept. would like to take the photo lab for its 3rd chem. lab to lower student numbers per classroom; Fine Arts Dept. would like to move photo lab to Bldg. 4 with the rest of the FA Dept.	
REQUESTED NEEDS	2	Chemistry Stockroom: Extra sink with an exhaust hood was requested.	
REQUESTED NEEDS	2	2301: Podium requested.	
REQUESTED NEEDS	2	Group Learning Classrooms (Flexible Classrooms) were requested.	
REQUESTED NEEDS	2	2204: Music staff lines needs to be on the board when ordered for the Fine Arts Dept.	
REQUESTED NEEDS	2	Outdoor Furniture Requested.	

REQUESTED NEEDS	3	3201: Room is dark; needs a better lighting system.	
REQUESTED NEEDS	3	3201: Chairs are uncomfortable for the students.	
REQUESTED NEEDS	3	Teachers need more writing space.	
REQUESTED NEEDS	3	New Curtains/Tinted Windows needed.	
REQUESTED NEEDS	3	General storage for backpacks/coats needed.	
REQUESTED NEEDS	3	Podium needed in 3201 that has media accessible.	
REQUESTED NEEDS	3	All computers with the ability to play DVDs.	
REQUESTED NEEDS	3	Request for student club to fund plants for classroom 3201.	
REQUESTED NEEDS	4	4104A: The possibility was raised whether this room could be made into the Fine Arts Photo Lab.	FA Photo Lab is currently in Building 2.
REQUESTED NEEDS	4	4104A/4104B: Flexibility for the 2 rooms to be used as one large classroom; this would mean the computers would have to be moved.	
REQUESTED NEEDS	4	Fine Arts would like a 25 station dark room added.	
REQUESTED NEEDS	4	4104A/4104B: No soundproofing between the two rooms; may need a sound divider on top.	
REQUESTED NEEDS	4	4201/4202: Need more natural lighting – window, maybe a patio with work area/studio.	
REQUESTED NEEDS	4	Interior Design needs more storage.	
REQUESTED NEEDS	4	4104B has no natural lighting; needs windows.	
REQUESTED NEEDS	4	4104B: Fixed classroom; cannot have group sessions or classroom discussions.	
REQUESTED NEEDS	4	4104B: Webster to be added?	
REQUESTED NEEDS	4	Ceramics Studio: More storage is needed.	
REQUESTED NEEDS	4	4304: Spotlights needed in ceiling.	
REQUESTED NEEDS	6	6204: Needs to be changed into a Smart Room.	
REQUESTED NEEDS	6	Elevator may be needed for Building 6; this may need to be included in the budget if state funding is not approved.	
REQUESTED NEEDS	6	Would like more space than the current 7000 sq. feet.	
REQUESTED NEEDS	6	Want to expand the labs.	
REQUESTED NEEDS	6	Possibility of making Bldg 6 a Linguistic and Cultural Center for Deaf Studies.	Deaf Studies Dept to supply a plan within 3-6 months.
REQUESTED NEEDS	6	Open to other languages using space as well.	
REQUESTED NEEDS	6	Gallaudet to move office and library to Bldg 6.	
REQUESTED NEEDS	6	New configuration of classrooms needed; all classrooms to have tele-conference abilities.	
REQUESTED NEEDS	6	Presently have 6 classrooms, would like to expand to 8-10. .	Largest class size is 20 students.

REQUESTED NEEDS	6	Room needed for staff and interpreters.	
REQUESTED NEEDS	6	6107: Physics Lab has no storage.	
REQUESTED NEEDS	6	6301: Engineering room is in bad shape. Power supply needed at desks and internet capability in classroom.	
REQUESTED NEEDS	8	Storage needed for backpacks/coats outside of classrooms.	
REQUESTED NEEDS	8	Benches are too close together.	
REQUESTED NEEDS	8	8201: Need to Purchase Bio Tech 2 free-standing tables and 4 Chairs.	
REQUESTED NEEDS	8	Natural Gas Bunsen Burners needed for Bio Tech.	
REQUESTED NEEDS	8	8201: Another deep sink.	
REQUESTED NEEDS	8	8304: Termites in the upper cabinets.	
REQUESTED NEEDS	8	Cabinets and drawers are too shallow/narrow.	
REQUESTED NEEDS	8	Need pull out shelves in bottom cabinets.	
REQUESTED NEEDS	8	8304: Refrigerator needed;no space in the room to place one.	
REQUESTED NEEDS	8	Cabinets need remodeled.	
REQUESTED NEEDS	8	8314: Power strips are too high.	
REQUESTED NEEDS	8	8305: Under-counter dishwasher needed.	
REQUESTED NEEDS	8	8305 & 8201 – Water softener needed?	
REQUESTED NEEDS	8	Split light control from the main room in all labs.	
REQUESTED NEEDS	8	8109: Receptacles needed on floor.	
REQUESTED NEEDS	8	8314/8315: Sink; Redo cabinets; need electrical outlets.	
REQUESTED NEEDS	8	8314: Skeleton models needs storage.	
REQUESTED NEEDS	8	8203: Ceiling space could be candidate for additional level.	
REQUESTED NEEDS	8	8314: No internet wiring; labs should be wireless.	
REQUESTED NEEDS	8	Microscope projection on screen for teaching.	
REQUESTED NEEDS	8	Better lighting control in labs.	
REQUESTED NEEDS	8	8315: Lack of storage; wooden shelf in a blind alley – need to be able to get around easier.	
REQUESTED NEEDS	8	Need storage for carts.	
REQUESTED NEEDS	8	Wood or plastic cabinets; current cabinets are not functional.	
REQUESTED NEEDS	8	8323: Needs locking drawers.	
REQUESTED NEEDS	8	8314: More storage needed to protect bones, which are irreplaceable.	
REQUESTED NEEDS	8	8314: Security of Power lab Hardware is inadequate.	
REQUESTED NEEDS	9	No windows in classrooms; classrooms are too dark.	
REQUESTED NEEDS	9	Classrooms could use plants, flexible furniture and new paint.	

REQUESTED NEEDS	9	Classrooms are not well soundproofed.	
REQUESTED NEEDS	9	9106 & Training Room: Remove Door between the two rooms and put up a new wall for better soundproofing.	
REQUESTED NEEDS	9	Dance Room: Needs new flooring.	
REQUESTED NEEDS	9	Dance/Aerobics Room needs more storage for equipment.	
REQUESTED NEEDS	9	9103a/9104a: Need whiteboards.	
REQUESTED NEEDS	9	9104a/9104b: Stereo System needs updating – maybe change over to satellite radio.	
REQUESTED NEEDS	9	Lighting needs improved.	
REQUESTED NEEDS	9	Install a ceiling to enclose the room.	
REQUESTED NEEDS	9	Training Room fan noise – may need balanced.	
REQUESTED NEEDS	9	9101: Healing Room with natural lighting.	
REQUESTED NEEDS	9	9101: Healing Room with dimmers for artificial lighting.	
REQUESTED NEEDS	9	9101: Healing Room with windows that open for natural air circulation.	
REQUESTED NEEDS	9	9101: Healing Room with possible door on west wall.	
REQUESTED NEEDS	9	Possible major remodel of 1st floor.	
REQUESTED NEEDS	9	Fitness Center needs paint.	
REQUESTED NEEDS	9	Fitness Center needs Ohlone College Logo.	
REQUESTED NEEDS	9	Fitness Center needs lights moved higher in the ceiling	
REQUESTED NEEDS	9	Fitness Center needs Sound System Upgrade (Satellite Radio?)	
REQUESTED NEEDS	9	Fitness Center needs Better Storage/Shelving	
REQUESTED NEEDS	9	Fitness Center needs TV's	
REQUESTED NEEDS	9	New Commercial Washer/Dryer needed & redesign of room.	
REQUESTED NEEDS	9	Offices need new paint.	
REQUESTED NEEDS	Hyman Hall	1st Floor: More controlled lighting throughout.	
REQUESTED NEEDS	Hyman Hall	Need more flexible classrooms.	
REQUESTED NEEDS	Hyman Hall	Lights are too bright in front of the classroom projectors. Suggestions for these lights to be placed on separate dimmers or taken out completely.	
REQUESTED NEEDS	Hyman Hall	Suggestion for more classroom lighting to be modeled after room 116.	
REQUESTED NEEDS	Hyman Hall	Open Lab: Over lit, take a look at the lighting system.	
REQUESTED NEEDS	Hyman Hall	Interpreter spotlighting needed during PowerPoint presentations.	
REQUESTED NEEDS	Hyman Hall	112: Inflexible classroom.	

REQUESTED NEEDS	Hyman Hall	Projection screens pull down directly over whiteboards, so that lecturers have to choose between using one medium over the other rather than having the option to use both simultaneously.	
REQUESTED NEEDS	Hyman Hall	118: More power supplies for laptops needed.	
REQUESTED NEEDS	Hyman Hall	116: Computers have not been upgraded in 4-5 years; suggestions for laptops versus desktops.	
REQUESTED NEEDS	Hyman Hall	116: Due to the inflexible classroom and abnormal layout, students have to keep moving to see their instructor, sometimes at uncomfortable angles to still be able to take notes at the same time.	
REQUESTED NEEDS	Hyman Hall	Suggestion for benches and plants to be added to the main lobby area.	
REQUESTED NEEDS	Hyman Hall	Suggestion for possible vending area somewhere in the building for students.	
REQUESTED NEEDS	Hyman Hall	Suggestion for an outside sitting area with picnic tables.	
REQUESTED NEEDS	Smith Center	Lobby carpet is deteriorating; needs replacing.	
REQUESTED NEEDS	Smith Center	Lobby is very small and would like to be expanded.	
REQUESTED NEEDS	Smith Center	Possible remodel of theater – add a balcony and approx. 100 seats.	Catwalks would need to be moved. Have tBP to look at this possible remodel for pricing, then look into donor for funding. An “escape” stairway would need to be added.
REQUESTED NEEDS	Smith Center	Replace outdoor truss.	
REQUESTED NEEDS	Smith Center	Add a permanent lighting tower.	
REQUESTED NEEDS	Smith Center	Additional wall protection – base boards.	
REQUESTED NEEDS	Smith Center	Possible theater storage in new parking structure.	
REQUESTED NEEDS	Smith Center	Curtains may need cleaned and fireproofed or replaced.	
REQUESTED NEEDS	Smith Center		